

温熱測定結果

—倉庫の熱画像撮影—

測定期間：

2015/7/31 9:00～18:00



測定箇所：1点

・天井中央

※断熱あり

※冷房、通風無し

この部分を表示



天井面の温度ムラはほぼ無し

Sp1 31.0 °C

40.0

Sp1
+



28.0



2015/7/31 9:00

Sp1 32.2 °C

40.0

Sp1
+



28.0



2015/7/31 10:00

Sp1

33.4

°C

40.0

Sp1



28.0



2015/7/31 11:00

Sp1 34.6 °C

40.0

Sp1
+



28.0

Sp1 35.5 °C

40.0

Sp1
+



28.0



2015/7/31 13:00

Sp1 36.3 °C

40.0

Sp1
+

28.0



2015/7/31 14:00

176°南

Sp1 37.0 °C

40.0

Sp1
+



28.0

 FLIR

2015/7/31 15:00

Sp1 37.0 °C

40.0

Sp1
+



28.0



2015/7/31 16:00

Sp1 37.4 °C

40.0

Sp1
+



28.0



2015/7/31 17:00

Sp1 37.3 °C

40.0

Sp1
+



28.0



2015/7/31 18:00